
CORNER RELORDS PAGE

CORNER RECORD

Agency Index Document Number 20190098 County of __PLACER City of UNINCORPORATED AREA California LOT 7 BLOCK "N" LAKE TAHDE PARK SUDIVISION NO. 1 Brief Legal Description BOOK 'D' OF MAPS PAGE 17 P.C.O.R. PER BOOK 23 OF SURVEYS PAGE 80 P.C.O.R. CORNER TYPE COORDINATES (Optional) SEC.13 Government Corner Control Elevation Unita ☐ Metric ☐ U.S. Survey Foot T.15N. Property Horizontal Datum □ R.16E. Rancho Zone _ Other Epoch Date M.D.M. Vertical Datum Date of Survey 9/12/19 ☐ Complies with Public Resources Code 8801-8891 □ Complies with Public Resources Code 8890-8902 П PLS Act Ref: X 8765(d) □ 8771 □ 8773 ☐ Other: Corner/ ☐ Left as found ☐ Rebuilt □ Established ☐ Pre-Construction Monument: ☐ Found and tagged Reestablished Referenced □ Post-Construction Narrative of corner identified and monuments as found, set, reset, replaced, or moved: ☐ See sheet #2 for description(s): ▶ = FOUND 2° IRON PIPE NO TAG, BELIEVE TO BE ORIGINAL PER *D*/MAPS/17 P.C.O.R. ■ = FOUND BATHEY MONUMENT (T-BAR) W/ NAIL & TAG STAMPED P.L.S. 8628 PER 23/SUR/80 P.C.O.R. = FOUND NAIL & TAG STAMPED P.L.S. 8628 PER 23/SUR/80 P.C.O.R. = FOUND 1/2" REBAR W/ WIRED TAG STAMPED L.S. 3229 PER 23/SUR/80 P.C.O.R. (R1) = RECORD PER BOOK 23 OF SURVEYS AT PAGE 80 P.C.O.R (R2) = RECORD PER BOOK "D" OF MAPS AT PAGE 17 P.C.O.R \mathcal{O} = SET BATHEY MONUMENT (T-BAR) W/ NAIL & TAG STAMPED P.L.S. 8628 JN:19079 SURVEYOR'S STATEMENT This Corner Record was prepared by me or under my direction in conformance with J KURT the Professional Land Surveyor's Act on NOVEMBER 22, MARKINAF 10.0026 COUNTY SURVEYOR'S STATEMENT This Corner Record was received DECEMBER 10,2019 No. 8373 County Surveyor's Comment



BPEL8G-2016

Page 2/2